



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Inspection Report Minerals Regulatory Program June 9, 2010

Reviewed: PPB

<b>Mine Name:</b> Beef Hollow Quarry	<b>Permit Number:</b> S/035/0040
<b>Operator Name:</b> CMC Rock Products	<b>Inspection Date:</b> April 22, 2010
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 9:00 am
<b>Other Participants:</b> none	<b>Mine Status:</b> Active

### Elements of Inspection

- Permits, Revisions, Transfer, Bonds
- Public Safety (shafts, adits, trash, signs, highwalls)
- Protection of Drainages / Erosion Control
- Deleterious Material
- Roads (maintenance, surfacing, dust control, safety)
- Reclamation
- Backfilling/Grading (trenches, pits, roads, highwalls, shafts)
- Soils
- Revegetation

### Evaluated

### Comment

### Enforcement

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 2014 **Bond Amount:** \$25,200 **Permit fee** is up to date

**Purpose of Inspection:** Routine annual Inspection. This site was inspected as a small mine site on 10/27/2009

**Inspection Summary:** Numerous stockpiles are in the area. Crushing equipment at the site has not been bonded for. Large Mine permit "Point West" NOI has yet to be completed. It appears that the disturbance is larger than 5 acres. Small areas adjacent to access road has been topsoiled and recently seeded, but roadway is not in the Beef Hollow NOI. There is no deleterious material on site. Every effort should be made to salvage top soil from the site prior to mining. Photos were taken to document site conditions.

**Conclusions and Recommendations:** Operator is to verify the disturbance at Beef Hollow is less than 5 acres as required for a small mine permit. Operator has 30 days to comply with all local, state and federal rules. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature**

*L. Heppler*

LAH:vs

cc: CMC Rock -Martin White

O:\M035-SaltLake\S0350040-BeefHollow\inspections\Insp-04222010.doc







Access Road



Highwall



Crushing equipment



Crushing equipment and Stockpiles